



### Noise Report from 11 June'18 to 15 June'18 (ie 5 days)



**High reading explanations :**

1. Use of vibrating hammer to install steel trench sheet in close proximity to Enviroguard 1.

