



Noise Report from 06 August'18 to 11 August'18 (ie 5.5 days)



High reading explanations :

1. Cutting reinforcement (disc cutter) adjacent to EnviroGuard 3.
2. Jet wash in use (due to inclement weather) adjacent to EnviroGuard 1.
3. Breaking up of ground slab with concrete breaker adjacent to EnviroGuard 1.

