



### Noise Report from 24 September'18 to 29 September'18 (ie 5.5 days)

Readings from 24-09-2018 08:00 for 5 days



#### High reading explanations :

1. Breaking up of ground slab/buried obstructions with concrete breaker adjacent to EnviroGuard 1.
2. Piling rig working immediately adjacent to EnviroGuard 2.

