



Noise Report from 04 February'19 to 08 February'19 (ie 5 days)

Readings from 04-02-2019 08:00 for 4 days



High reading explanations :

1. Cutting of reinforcement in close proximity to noise recorders.

