



Noise Report from 13 August'18 to 17 August'18 (ie 5 days)



High reading explanations :

1. Airlance being used to blow out capping beam immediately adjacent to EnviroGuard 3
2. Breaking up of ground slab with concrete breaker adjacent to EnviroGuard 1.

