



Noise Report from 17 September'18 to 24 September'18 (ie 5.5 days)

Readings from 17-09-2018 08:00 for 5 days



High reading explanations :

1. Breaking up of ground slab/buried obstructions with concrete breaker adjacent to EnviroGuard 1.

