



Noise Report from 22 October'18 to 27 October'18 (ie 5.5 days)



High reading explanations :

1. Cropping of piles & drilling between piles to insert land drains.

