



Noise Report from 08 October'18 to 13 October'18 (ie 5.5 days)

Readings from 08-10-2018 08:00 for 5 days



High reading explanations :

- Concrete agitator located immediately adjacent to EnviroGuard 3.

