



Noise Report from 04 June'18 to 09 June'18 (ie 5.5 days)



High reading explanations :

1. Use of mechanical torque wrench (nut runner) for bolting up steel gantry in close proximity to Enviroguard 1.

